



## Retrofit Solution for Siemens 805 Controls

### The Hydromat® CNC Stand Alone Machining Unit (Factory Revised\*)

#### Why the retrofit solution?

- ▶ After 20 years of operation of the Siemens CNC control 805 at Pfiffner, the service activity for this type of control has been mechanically as well as on the control side discontinued.
- ▶ There are many reasons for this. Among other things, spare parts or individual components are no longer available by the manufacturer.
- ▶ In addition, due to the change in generations of our employees, we are no longer able to maintain the service for this technology.

#### Your solution for the future

- ▶ Hydromat® CNC stand alone machining unit with side cabinet.
- ▶ Special offer price, incl. start-up and training for € 79.900,-, temporally limited until 31.12.2022.
- ▶ Payment in instalments (€ 84.000,-) possible as an option. € 48.000,- down payment / 12 instalments of € 4.000,- each. First down-payment due 30 days after start-up.

\* Basis is an exchange unit, factory-revised

# Overview Pfiffner Supply of Services

## Service Products

- ▶ Replacement of control panel
- ▶ Replacement Siemens 805
- ▶ ReVest®
- ▶ Repair Express
- ▶ Sawing unit, reinforced expansion stage
- ▶ CNC stand alone machining unit
- ▶ Test bench
- ▶ TENDOturn spindle uprating
- ▶ Inverting unit monitored
- ▶ High-pressure collet flushing
- ▶ Rent instead of buy

## Control / Teleservice / Security

- ▶ Pfiffner Remote Service (data glasses)
- ▶ Fingerprint
- ▶ Inspection, prevention pays off
- ▶ Maintenance agreement, prevention pays off
- ▶ Customer training
- ▶ Call Teleservice
- ▶ Safety inspection
- ▶ Teleservice box
- ▶ Energy efficiency subsidies

